

ORIGINAL



0000073210

BEFORE THE ARIZONA CORPORATION COMMISSION

RECEIVED

**COMMISSIONERS**

Mike Gleason, Chairman  
William A. Mundell  
Jeff Hatch-Miller  
Kristin K. Mayes  
Gary Pierce

2007 MAY 18 P 4: 04

AZ CORP COMMISSION  
DOCKET CONTROL

IN THE MATTER OF THE APPLICATION OF  
WATER UTILITY OF GREATER TONOPAH,  
INC., AN ARIZONA CORPORATION, FOR AN  
EXTENSION OF ITS EXISTING CERTIFICATE  
OF CONVENIENCE AND NECESSITY.

Docket No. W-02450A-06-0626

**NOTICE OF FILING**

The Water Utility of Greater Tonopah ("Tonopah") provides notice of filing of the attached compliance status reports from the Maricopa County Environmental Services Department (MCESD). The reports are for the following systems:

System	PWS No.	Status
Garden City	07-037	Compliant
Dixie	07-030	Compliant
Sunshine	07-071	Compliant
Roseview	07-082	Compliant
B&D	07-618	Complaint
WPE # 6	07-733	Complaint

Tonopah has a seventh system, WPE # 7 that is not a community system and is therefore not regulated by MCESD. Therefore, no report can be provided for that system. Thus, all six systems regulated by MCESD are considered "compliant" by MCESD.

...

...

...

...

Arizona Corporation Commission  
**DOCKETED**

MAY 18 2007

DOCKETED BY

ne

1 RESPECTFULLY SUBMITTED this 18<sup>th</sup> day of May 2007.

2  
3 ROSKA DEWULF & PATTEN, PLC

4  
5  
6 By 

7 Timothy J. Sabo  
8 One Arizona Center  
9 400 East Van Buren Street, Suite 800  
10 Phoenix, Arizona 85004

11 Original + 13 copies of the foregoing  
12 filed this 18<sup>th</sup> day of May 2007, with:

13 Docket Control  
14 Arizona Corporation Commission  
15 1200 West Washington  
16 Phoenix, Arizona 85007

17 Copies of the foregoing hand-delivered/mailed  
18 this 18<sup>th</sup> day of May 2007, to:

19 Lyn A. Farmer, Esq.  
20 Chief Administrative Law Judge  
21 Hearing Division  
22 Arizona Corporation Commission  
23 1200 West Washington  
24 Phoenix, Arizona 85007

25 Christopher C. Kempley, Esq.  
26 Chief Counsel, Legal Division  
27 Arizona Corporation Commission  
1200 West Washington  
Phoenix, Arizona 85007

Ernest G. Johnson, Esq.  
Director, Utilities Division  
Arizona Corporation Commission  
1200 West Washington  
Phoenix, Arizona 85007

By 

ROSKA DEWULF & PATTEN, PLC  
ONE ARIZONA CENTER  
400 EAST VAN BUREN STREET - SUITE 800  
PHOENIX, ARIZONA 85004  
TELEPHONE NO 602-256-6100  
FACSIMILE 602-256-6800



**Maricopa County**  
Environmental Services Department

**PUBLIC WATER SYSTEM COMPLIANCE STATUS REPORT**

**System Name:** Water Utilities of Tonopah  
**PWS ID#:** 07-037

Type of System: Community Number of POE's: 1 Surface Water: n/a  
Number of Service Connections: 16 Population Served: 51

Assigned Monitoring Dates - Initial: 1/1/98 Phase II: 1/1/98 Phase V: 1/1/98

Does the water system have a Certified Operator? Yes

Does the system have major treatment plant deficiencies? No  
Please describe: \_\_\_\_\_

Date of last inspection: November 15, 2007

Does the system have major O & M deficiencies? No  
Please describe: \_\_\_\_\_

Does the system have water quality monitoring/reporting deficiencies? No  
Please describe: \_\_\_\_\_

General Public Water System Compliance Status? Compliant

Date of compliance review: 4/11/2007 By: Duncan Wright Initials: dw  
Phone: (602) 506-5173

Requested By: Global Fax Number/ Contact: \_\_\_\_\_ Tracking Number: 1298  
Supervisor Initials: GY Date: 4/11/07

**Drinking Water Program**  
**John Kolman, Manager**

1001 N. Central Ave., Suite 150 Phoenix, Arizona 85004-1940 Phone: (602) 506-6666 Fax: (602) 506-6925



**Maricopa County**  
Environmental Services Department

**PUBLIC WATER SYSTEM COMPLIANCE STATUS REPORT**

**System Name:** Water Utility of Greater Tonopah – Dixie Water  
**PWS ID#:** 07-030

Type of System: Community Number of POE's: 1 Surface Water: no  
Number of Service Connections: 26 Population Served: 81

Assigned Monitoring Dates - Initial: 1/1/99 Phase II: 1/1/99 Phase V: 1/1/99

Does the water system have a Certified Operator? yes

Does the system have major treatment plant deficiencies? no  
Please describe: \_\_\_\_\_

Date of last inspection: 3/6/07

Does the system have major O & M deficiencies? no  
Please describe: \_\_\_\_\_

Does the system have water quality monitoring/reporting deficiencies? no  
Please describe: \_\_\_\_\_

General Public Water System Compliance Status? Compliant

Date of compliance review: 3/21/07 By: Laura Moorhead Initials: \_\_\_\_\_  
Phone: (602) 506-6631

Requested By: ACC Fax Number/ Contact: \_\_\_\_\_ Tracking Number: 1280  
Supervisor Initials: GY Date: 3/23/07

Drinking Water Program  
John Kolman, Manager

1001 N. Central Ave., Suite 150 Phoenix, Arizona 85004-1940 Phone: (602) 506-6666 Fax: (602) 506-6925



**Maricopa County**  
Environmental Services Department

**PUBLIC WATER SYSTEM COMPLIANCE STATUS REPORT**

**System Name:** WUGT - Sunshine Water Company  
**PWS ID#:** 07-071

Type of System: Community Number of EPDS's: 1 Surface Water: N/A  
Number of Service Connections: 117 Population Served: 362

Assigned Monitoring Dates - Initial: 1/1/94 Phase II: 1/1/94 Phase V: 1/1/94

Does the water system have a Certified Operator? yes

Does the system have major treatment plant deficiencies? No  
Please describe: \_\_\_\_\_

Date of last Sanitary Survey: November 15, 2005

Does the system have major O & M deficiencies? No  
Please describe: \_\_\_\_\_

Does the system have water quality monitoring/reporting deficiencies? No  
Please describe: System is reporting arsenic levels that may be higher than MCL after further submittal and quarterly averaging. System has submitted a blending plan to address high arsenic levels but has not fulfilled requirements for approval of the plan.

General Public Water System Compliance Status? Compliant

Date of compliance review: March 28, 2006 By: Rob Collins Initials: \_\_\_\_\_  
Phone: (602) 506-0719

Requested By: Dorothy Hains, ACC Fax Number/ Contact: :602 542 0766 Tracking Number: 1284  
Supervisor Initials: GY Date: 3/30/07

**Drinking Water Program**  
**John Kolman, Manager**

1001 N. Central Ave., Suite 150 Phoenix, Arizona 85004-1940 Phone: (602) 506-6666 Fax: (602) 506-6925



**Maricopa County**  
Environmental Services Department

**PUBLIC WATER SYSTEM COMPLIANCE STATUS REPORT**

**System Name:** WUGT- Rose View Water  
**PWS ID#:** 07- 082

Type of System: Community Number of POE's: 1 Surface Water: No  
Number of Service Connections: 51 Population Served: 16

Assigned Monitoring Dates - Initial: 1/1/02 Phase II: 1/1/02 Phase V: 1/1/02

Does the water system have a Certified Operator? Robert Garcia: 623-386-4252 x-106

Does the system have major treatment plant deficiencies? N/A  
Please describe: \_\_\_\_\_

Date of last inspection: November 15, 2005

Does the system have major O & M deficiencies? None  
Please describe: All deficiencies from 11/15/05 inspection corrected per system letter in file dated: 12/21/05

Does the system have water quality monitoring/reporting deficiencies? Note:  
Please describe: System has arsenic levels which will violate the new standard eff 12/31/07

General Public Water System Compliance Status? Compliant

Date of compliance review: 03/21/07 By: Mike Mallette Initials: MKM  
Phone: (602) 506-6644

Requested By: Dorothy Haines  
Fax Number/ Contact: 602-542-7274 Tracking Number: 1282  
Supervisor Initials: GY Date: 3/23/07

**Drinking Water Program**  
**John Kolman, Manager**

1001 N. Central Ave., Suite 150 Phoenix, Arizona 85004-1940 Phone: (602) 506-6666 Fax: (602) 506-6925



**Maricopa County**  
Environmental Services Department

**PUBLIC WATER SYSTEM COMPLIANCE STATUS REPORT**

**System Name: B&D/Buckeye Ranch**  
**PWS ID#: 07-618**

Type of System: Community Number of POE's: 2 Surface Water: no

Number of Service Connections: 92 Population Served: 285

Assigned Monitoring Dates – Initial: 1998 Phase II: 1998 Phase V: 1998

Does the water system have a Certified Operator? D. Blain Harold

Does the system have major treatment plant deficiencies? no  
Please describe:

Date of last inspection: 2/20/07

Does the system have major O & M deficiencies? minor  
Please describe: Buckeye Ranch site booster 2 has leak that needs repair

Does the system have water quality monitoring/reporting deficiencies? no  
Please describe:

General Public Water System Compliance Status? Compliant

Date of compliance review: 2/21/07 By: **Laura Moorhead** Initials: \_\_\_\_\_  
Phone: (602) 506-6631

Requested By: post-insp Fax Number/ Contact: \_\_\_\_\_ Tracking Number: 1268  
Supervisor Initials: GY Date: 2/22/07



**Maricopa County**  
Environmental Services Department

**PUBLIC WATER SYSTEM COMPLIANCE STATUS REPORT**

**System Name:** West Phoenix Estates #6  
**PWS ID#:** 07-733

Type of System: Community Number of POE's: 1 Surface Water: no  
Number of Service Connections: 23 Population Served: 71

Assigned Monitoring Dates - Initial: 1/1/02 Phase II: 1/1/02 Phase V: 1/1/02

Does the water system have a Certified Operator? yes

Does the system have major treatment plant deficiencies? no  
Please describe: \_\_\_\_\_

Date of last inspection: August 19, 2005

Does the system have major O & M deficiencies? no  
Please describe: \_\_\_\_\_

Does the system have water quality monitoring/reporting deficiencies? no  
Please describe: \_\_\_\_\_

General Public Water System Compliance Status? Compliant

Date of compliance review: 3/20/07 By: Laura Moorhead Initials: \_\_\_\_\_  
Phone: (602) 506-0462

Requested By: ACC Fax Number/ Contact: \_\_\_\_\_ Tracking Number: 1281  
Supervisor Initials: GY Date: 3/21/07

**Drinking Water Program**  
**John Kolman, Manager**

1001 N. Central Ave., Suite 150 Phoenix, Arizona 85004-1940 Phone: (602) 506-6666 Fax: (602) 506-6925